
**International Business Department
Advanced Automation Company**

No. 08-A-0066E

Date: July 2, 2008
To: Those listed
Issued by: T. Kurasawa, General Manager
Subject: R7259B/R7257A Flame Amplifier Obsolescence
Summary: R7259B and R7257A Flame Amplifiers will be discontinued on September 30, 2008.

Background: Seven years have passed since WN210/WN200 Flame Modules were discontinued, and five years have passed since the R4150P Protectorelay was discontinued. R7259B/R7257A Flame Amplifiers for WN210/WN200 and R4150P models will now be discontinued as scheduled.

The WN210 and WN200 have been replaced by the FRS100 Flame Relay. In instrumentations with higher safety requirements, they have been replaced by the AUR Advanced UV Detector. R4150P has been replaced by the R4780 Protectorelay. These replacement models have already been accepted in the field.

Required actions:

- i) Check the notification destinations, including maintenance and procurement divisions.
- ii) If the user will order a large number of R7259B/R7257A amplifiers as spares in operating facilities, contact us in advance.

Schedule:

Orders: Until September 30, 2008