

## AAC Marketing Bulletin

---

Date:	Dec. 1, 2011	Publ. No.	11-A-0166E
Supervisor:	H. Goto, Mktg. Dept., Ctrl./Mgmt. Gr. 2	Indiv. No./Model No.:	C7035/C7027/129464NJ
Issued by:	T. Sato, S. Kadoya, Mktg. Dept., Ctrl./Mgmt. Gr. 2	Class./BU category:	FSG

### **Order procedure for discontinuation of Minipeeper Ultraviolet Flame Detectors (C7035/C7027/129464NJ)**

#### **1. Overview**

We will discontinue handling the sale of C7035 and C7027 Minipeeper Ultraviolet Flame Detectors and 129464NJ spare UV tube at the end of Dec. 2011.

Please note that orders cannot be entered after Jan. 2012.

#### **2. Background**

As announced in the Nov. 2011 Marketing Bulletin (11-A-0142) regarding the discontinuation of Minipeeper Ultraviolet Flame Detectors (C7035/C7027/129464NJ), many of our customers have already replaced Minipeeper Ultraviolet Flame Detectors with the AUD100 Series Advanced Ultraviolet Flame Detectors using Yamatake-manufactured UV sensors. We have decided to streamline our product offering and focus on the sale of the AUD100 series detectors for batch operation.

#### **3. Requirements/actions**

- Please be sure to notify your customers of the discontinuation of C7035/C7027/129464NJ and of the switchover to the AUD100 series detectors.
- Please recommend the AUD100 series detectors to customers who order C7035/C7027/129464NJ.
- From Jan. 2012, orders for C7035/C7027/129464NJ cannot be entered. Please reenter the order for the AUD100 series.

#### **4. Time of discontinuation**

Last day to order : Dec. 28, 2011

Last day for delivery: March 30, 2012

\*Orders received after Jan. 2012 cannot be entered.

## 5. Discontinued model numbers and alternative model numbers

<b>Discontinued model number</b>	<b>Alternative model number (UV tube + socket)</b>
129464NJ	AUD15C1000
C7035A1064J	AUD100C1000+AUD15C1000 or AUD100C1000-A15 (Model no. including AUD15)
C7035A500J	AUD110C1000+AUD15C1000 or AUD110C1000-A15 (Model no. including AUD)
C7027A1072J	AUD100C1000+AUD15C1000+FSP100R15000

-End-