

PREX 3000 CONVERTER

6) MULTI - I / P Converter

Basic Model No Selection Option
 Model No. : KUX111 - I II III IV V V - V

Description	Selection																			VII Options			
	I Power Source	II Inp ut	III Output				IV Conne ction-		V Module								VI Mount ing		Environmen				
Model No. Ex KUX111 - X11A5CX - X	None	4 to 20mA DC	0.2 to 1.0kgf / cm ²	3 to 15psi	0.2 to 1.0 bar	20 to 100kPa	Rc 1 / 4	a / 4 NPT internal thread	File only	File + 1 Converting Modules	File + 2 Converting Modules	File + 3 Converting Modules	File + 4 Converting Modules	File + 5 Converting Modules	File + 6 Converting Modules	File + 7 Converting Modules	File + 8 Converting Modules	19 - inch rack mount	Wall mount	Standard	For tropical service	Corrosive atmosphere	No option
Notes) IV : Air Connection																							
Model No.	- X	1	1	2	3	4	A	B	0	1	2	3	4	5	6	7	8	C	S	X	A	B	- X
Basic Price	0	0	0	0	0	0	0	0	- 88	0	88	176	264	352	440	528	616	0	0	0	*	*	0
Model No.																							
MULTI - I / P Converter	KUX111	341	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			✓

* quoted upon request

7) MULTI - I / P Converter Module

Basic Model No Selection Option
 Model No. : KUX118 - I II III IV - V

Description	Selection										V Options
	I Power Source	II Inpu	III Output				IV Environmen				
Model No. KUX118 - X11X - X	None	4 to 20mA DC	0.2 to 1.0kgf / cm ²	3 to 15psi	0.2 to 1.0bar	20 to 100kPa	Standard	For tropical service	Corrosive atmosphere	No option	
Model No.	- X	1	1	2	3	4	X	A	B	- X	
Basic Price	0	0	0	0	0	0	0	*	*	0	
Model No.											
MULTI - I / P Converter Module	KUX118	156	✓	✓	✓	✓	✓	✓		✓	

* quoted upon request