

# PREX 3000 CONVERTER

## 8) Single - I / P Converter

Basic Model No. Selection Option  
 Model No. : KUX112 - I II III IV V VI - VI

Description	Selection													VII Options
	I Power Source	II Input	III Output				IV Connection		V Mounting	VI Environment				
Model No. Example KUX112 - X11ASX - X  Notes) IV : Air Connection	None	4 to 20mA DC	0.2 to 1.0kgf / cm <sup>2</sup>	3 to 15psi	0.2 to 1.0bar	20 to 100kPa	Rc 1 / 4	1 / 4 NPT, internal thread		Wall mount, indoor installation	Standard	For tropical service	Corrosive atmosphere	No option
Model No.	X	1	1	2	3	4	A	B		S	X	A	B	- X
Basic Model No.	Price	0	0	0	0	0	0	0		0	0	*	*	0
SINGLE - I / P Converter	KUX112	227	a	a	a	a	a	a	a	a	a			a

\* quoted upon request

## 9) FIELD - TYPE I / P Converter

Basic Model No. Selection Option  
 Model No. : KUX113 - I II III IV V VI - VI

Description	Selection																	VII									
	I Power source	II Case			III Input	IV Output							V Connection	VI Environment			Options										
Model No. Ex. KUX113 - XW11AX - X	None	Weather proof type	TIIS Flameproof type	TIIS Intrinsically Safe type	FMI Explosion proof type	FMI Intrinsically Safe type	4 to 20mA	0.2 to 1.0 kgf / cm <sup>2</sup>	3 to 15 psi	0.2 to 1.0 bar	20 to 100 kPa	19.6 to 98.1 kPa	20 to 100kPa Double scale (kPa/kgf/cm <sup>2</sup> )	0.2 to 1.0kPa Double scale (kPa/kgf/cm <sup>2</sup> )	Air connection Rc 1 / 4	Air connection 1 / 4 NPT	Standard	Corrosion resistant paint	Heavy corrosion resistant paint	Silver finish	No option	With one flameproof packing (Available for TIIS Flameproof only)	With output gauge	With by - pass set	With Pressure regulator with filter	With air piping elbow (material : SUS304)	1/2 NPT internal thread electrical conduit (Not available for TIIS Flameproof only)
Model No.	- X	W	E	H	F	M	1	1	2	3	4	8	A	D	A	B	X	A	B	D	X	P	G	6	7	J	N
Basic Model No.	Price	0	0	5	5	15	15	0	0	0	0	0	0	5	5	0	0	0	10	15	8	0	10	11	26	2	0
FIELD - TYPE I / P Converter	KUX113	286	a	a	a	a	a	a	a	a	a	a	a	a	a	a	a	a	a	a	a	a	a			a	a