

Notification Concerning AUD100 Series Advanced Ultraviolet Flame Detectors

Thank you for your continuing use of our products. In the near future, we will discontinue the sale of Minipeper Ultraviolet Flame Detectors in order to focus on maintaining quality production and stable supply of the more reliable AUD100 Series Advanced Ultraviolet Flame Detectors.

1. Discontinuance of the sale of the old models will start at the end of December 2011.
2. Comparison table between the old model numbers and new ones.

Old product model No.*	Model numbers of new product (UV tube + socket)
C7035A1064J	AUD15C1000 + AUD100C1000 (lead wire model)
C7035A500J	AUD15C1000 + AUD110C1000 (terminal block model)
129464NJ	AUD15C1000
C7027A1072J	AUD15C1000 + AUD100C1000 (lead wire model) + FSP100R15000 (AUD100 G1/2 Adapter)

**(1) AUD100 series: Combination of a new UV tube and a new socket**

Compatible



AUD15C1000

+



AUD100C1000

**(2) Combination of a new UV tube and an old socket**

\*We recommend combination with a new socket.

Compatible



AUD15C1000

+



C7035A1064J

**(3) Combination of an old UV tube and a new socket**

Not Compatible



129464NJ

+



AUD100C1000